

## EXCAVATION WORK



Total commitment to the Golden Rules



- comprising a map of all buried hazards.
- Apply precautions for work in confined spaces, as necessary.
- Clearly mark all excavation areas and identify underground structures.

• Place machinery or spoil piles within one meter of a trench being excavated.



