




7 POWERED SYSTEMS



Total commitment to the Golden Rules



Design and Production: www.because.fr - Photo credit: J. Muguet © TOTAL - March 2017



YOU MUST:

- Follow the isolation plan and supervision instructions attached to the work permit.
- Check all isolations, locks and tags before performing any work and remove them before restarting operations.



YOU MUST NOT:

- Begin any work until you have checked that all energy and fluid sources have been isolated, unless you are specifically authorized to do so.

